

Capricorn Contract & Supplies Ltd

Cleaning, Protecting & Care Treatment of Ceramic Tiles, Slabs
Terracotta, Terrazzo, Natural & Artificial Stone, Concrete Slabs

Project Restoration 15 Offices London



Granite vanity units with heavy limescale deposits that had eaten into the surface this had caused a very unsightly mark across the granite and in some places damaged the stone



The granite was badly pitted by the limescale and therefore had to be diamond cut and then polished to restore the surface. The granite was then sealed with Fila Hydrorep impregnating seal and given a final polish.

Unit 4 Chipperfield Business Park, Tower Hill, Chipperfield, Herts WD4 9LH
Tel 01442 831200 Fax 01442 831999 email info@capricorncontracts.co.uk