

# **Capricorn Contract & Supplies Ltd**

**Cleaning, Protecting & Care Treatment of Ceramic Tiles, Slabs  
Terracotta, Terrazzo, Natural & Artificial Stone, Concrete Slabs**

## **Project Restoration 4**

## **London**



*Marble floor damaged with scratch marks and incorrect seal applied causing the floor to go dull with swirl marks.*

*The floor was chemically Stripped to remove the seal And then acid etched to Remove the scratches and Bring back the shine, the floor was then sealed. The photo above shows the final etching sequence.*

