

Capricorn Contract & Supplies Ltd

**Cleaning, Protecting & Care Treatment of Ceramic Tiles, Slabs
Terracotta, Terrazzo, Natural & Artificial Stone, Concrete Slabs**

Project Restoration 5

London



Machined Terracotta floor badly damaged by acidic cleaners used for cleaning the floor, the seal had been removed this allowed staining to penetrate the terracotta. The surface of the tile had also been damaged by the cleaners used.

The Terracotta was first skimmed to remove the damaged surface then the surface was bonded to prevent further damage to the tile.

Hot wax treatment was then applied and a final treatment before buffing the floor to the required finish.

