

Capricorn Contract & Supplies Ltd

Cleaning, Protecting & Care Treatment of Ceramic Tiles, Slabs
Terracotta, Terrazzo, Natural & Artificial Stone, Concrete Slabs

Project Restoration

2

Watford



Hand made Terracotta floor with excess grout covering the surface and a wax seal put on on top. the floor looked very dirty and was not properly sealed thus allowing stains to penetrate.

The floor was first cleaned and stripped of all finishes, it was then treated to remove the grout residue, once cleaned the floor was dried, waterproofed and then a base wax applied, a final finish was put on and then buffed to required finish.

